

## **Majestic Manufacturing, Inc.**

Majestic Manufacturing, Inc. \* PO Box 128  
4536 State Route 7, New Waterford, Ohio 44445

**Subject:** Folding Gooseneck Supplement

**ATTN: OWNER/OPERATOR**

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin **must** remain with the owner's manual at **all** times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m.-4:30p.m. E.S.T. \*\* Fax 330/457-7490.

## **SERVICE BULLETIN**

**Date:** May 1, 1991

**S.B. Number:** S.B. 91-2 Supplement to Service Bulletin 91-2

**Notice:**

Service Bulletin 91-2 and the safety decal referred to; emphasize the importance of maintaining the gooseneck assembly to factory standards. This supplement letter is being supplied to all of our customers explaining what the phrase "FACTORY STANDARDS" means.

1. Inspect the shock absorbers to see that they are in good condition and installed correctly.
2. King pin is free of weld cracks or abnormal wear.
3. Pivot arms must be free of weld cracks and end caps must be in place.
4. Pivot brackets must be free of weld cracks.
5. Folding support plate must be free of weld cracks and any excessive wear on pipe ends.
6. Safety lock bar must be installed and in good condition.
7. Drive pins must be installed and in good condition.
8. Drive pin locks are to be free of weld cracks and in good condition.
9. Mechanical stabilizer must be in place at all times and in good condition.

**NOTE:** SERVICE BULLETINS 91-2 AND 91-4 MUST BE COMPLIED WITH FOR A SAFE GOOSENECK OPERATION.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.