

Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. * PO Box 128
4536 State Route 7, New Waterford, Ohio 44445

Subject: General Inspection

ATTN: OWNER/OPERATOR

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin **must** remain with the owner's manual at **all** times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m.-4:30p.m. E.S.T. ** Fax 330/457-7490.

SERVICE BULLETIN

Date: April 25, 1996

S.B. Number: 96-2

Notice:

This service bulletin is to inform all owner/operators with Majestic Bumper Cars that a general inspection of each and every bumper car should take place prior to each operation.

Areas to inspect prior to each operation:

1. Check to see that all safety equipment is in it's place and operational.
2. Steering wheel pad (proper size).
3. Stinger pole pads are appropriate for the car type.
4. Hand holds, padded dash.
5. Seatbelts and/or lap bars are functional.
6. Entire interior of car has no loose objects, etc.
7. Mechanical aspect of each car is in good working order.
8. Electrical aspect of each car is in good working order.
9. Bumper tire is properly inflated at 10 P.S.I.

This is a basic guideline of safety awareness for all owner/operator's with the purpose of inspecting each car for the customers safety.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.